Product Data Sheet Stability Engineered Planks - Finish BF925





Image shows Prime option.

Product Details

Product Description:	Stability 15 / 20
Wood Species:	European Oak
Construction:	Engineered
Product Type:	Planks
Grade:	Prime / Rustic
Profile:	Tongue & Grooved
Edge Profile:	Ends Matched & 1.50mm Micro Bevelled to Long Edges
Finish:	BF925 UV Oiled - Tumbled Light Smoked* White Silk
Total Thickness:	15mm
Width/s:	140 / 180 / 220mm
Length/s:	Random 600 - 2200mm (Average 1800mm)
Wear Layer:	4mm Oak Wear Layer
Core Layer:	11mm Multi Layer Birch Plywood
Total Thickness:	20mm
Width/s:	140/160"/180/200"/220/240/260/300mm
Length/s:	Random 1400 - 2400mm (Average 1800 - 2200mm)
Wear Layer:	6mm Oak Wear Layer
Core Layer:	14mm Multi Layer Birch Plywood

* Our fumed and smoked colours are achieved through a process which reacts with the natural tannins in the oak. Although we use controlled processes when smoking **variation in colour will occur** and the final colours are dictated by nature and not by using pigmented stains.

" All widths available from stock apart from 160 & 200mm in rustic grade, this is to order.



Should you require the information on any other details please contact the sales team on **020 8501 6730** or **info@wfa.uk.net**



Technical Information - Birch Plywood

Country of Manufacture:	Europe			
FSC [®] :	FSC 100% FSC-C111710			
Lamination:	Hydraulic Cold Press			
Glue Line:	D3 Water Based Glue			
Norm:	EN 14342:2013			
Reaction to Fire:	15mm D _{fl} -s1 / 20mm C _{fl} -s1			
Density:	650 kg/m3			
Formaldehyde Emissions:	Class E1 Zero Emissions			
Warmth Conduction (approx):	15mm – 0.111 W/m K			
	20mm – 0.148 W/m K			
Production Tolerances;				
Width:	+/- 0.2mm			
Thickness (Above T&G):	+/- 0.2mm			
Length:	+/- 3.0mm			
90° Angle:	+/- 0.30			

Grading

PRIME

Maximum Size of Sound Knots: Possible knots up to 10mm

Possible knots up to 5mm
Not Allowed
Minimal Edge and Core Sap Wood
Natural Variation Allowed
Mixture of Natural Grain

RUSTIC

Maximum Size of Sound Knots: Up to 70mm

Maximum Size of Filled Knots:	Up to 35mm
Filled Defects:	Allowed
Filled Type:	Coloured Filler
Sap Wood:	Minimal Edge and Core Sap Wood
Cracks:	Possible
Colour Variation:	Natural Variation Allowed
Grain Variation:	Mixture of Natural Grain and Knots

© This technical data sheet was written by Wood Floors and Accessories Limited. At the time of writing and publication of the sheet, all information is specified correctly. The company reserves the right to change the specifications of this product at any time without prior notice to third parties. The images used on this sheet are for guidance purposes only. No rights can be derived from them. **Installation and Warranty**: The Wood Floors and Accessories warranty only applies to floors that have been installed by a competent flooring installer with the skills and knowledge to take into account individual site circumstances. This is in accordance with and comparable to BS 8201:2011 in the UK or equivalent standards worldwide.

Product Data Sheet Stability Engineered Planks - Finish BF925





Image shows Prime option

Installation

Installation Method:	Glued	Nailed	Floated on Underlay
Please also refer to our guidelines.	\checkmark		\checkmark

NOTE: The fully bonded method of installation is recommended.

Over Underfloor Heating: When glued to an appropriate subfloor this product is suitable for use with water and some electric systems. Floor probes must be installed to control and regulate the flooring temperature which must not exceed 27°C. We also highly recommend the installation of a data recording Fidbox which measures and logs the temperature and humidity levels, see the data sheet for more information or www.floorprotector.at

Site Conditions: 45 – 65% relative humidity & 15 – 25°C room temperature.

Throughout the life of the floor, we recommend that the temperature should be maintained between 15°C and 25°C, and relative humidity levels between 45% and 65%, which will keep any movement within the floor to a minimum and ensure that the floor remains stable. As with any wooden floor, if humidity levels rise or fall outside of these parameters, a greater degree of shrinkage or expansion would be expected to occur.

For the complete installation guidelines please visit www.wfa.uk.net



Should you require the information on any other details please contact the sales team on **020 8501 6730** or **info@wfa.uk.net**



Maintenance Advice

To fully aid in the care of the floor it is advised that all precautions are carried out. Avoid scratches by minimising grit and dust, install doorway entrance mats and apply felt pads to furniture. Use PH neutral cleaners and avoid soaking the floor with water at all times.

Recommended Products	Initial	Regular	Monthly	Long Term
Sweep / Vacuum:	1	1		
Oiled Finish				
Osmo Wash and Care:		1		
Osmo Maintenance Oil:				1

For the complete maintenance guidelines please visit www.wfa.uk.net



Wood Floors & Accessories Limited guarantees to investigate any complaints reported within 25 years from the date of your sales invoice. In the event of a valid claim, Wood Floors & Accessories Limited will provide replacement material free of charge.

The lifetime of our guarantee covers the structural integrity of the product being the lamination, production, dimensions and grading.

For pre-finished floors our guarantee also covers that the surface finish will adhere correctly to the boards. It is however essential that a preventative cleaning and maintenance program is in use as set out in clause 4 & 5 of our terms and conditions.

Wood is a natural product and will expand and contract throughout the four seasons. During these seasons, you may experience some natural movement which is not a product defect and is not covered by this guarantee.

As a general guideline, the ambient room temperature should be maintained between 15 and 25°C and humidity levels between 45 and 65%. To maintain these humidity levels, we would recommend using a humidifier/dehumidifier. Our guarantee is subject to your room conditions being maintained in accordance with British Standards current recommendations.

All complaints are to be reported in writing by post or email to info@wfa.uk.net within 48 hours of the issue becoming visible, to allow us to investigate the cause and extent of the problem.